



CM12320

SFERA

500, 600 - PC1172, PC1284



Download

COMPONENTS INCLUDED WITH UNIT:

1× light, 1× ceiling canopy, 1× plastic cable stop
1× power cable, 1× fixture cover, 1× inner fixture
3× stainless-steel wire ropes
3× brass balls, 1× hex key size 1.5
1× hex key size 2, 1× hex key size 2.5
3× set screws M5×16
3× installation hooks, 1× spirit level
1× pair cotton gloves
1× installation manual

WARNING:

Installation must be carried out by a qualified electrician only.

Switch off power at main circuit panel prior to installation!

The manufacturer assumes no liability for damage occurring in transport or resulting from incorrect installation.

LIGHT SOURCE NOT INCLUDED.

Installation time: 30 minutes / 2 persons



BROKIS®

BROKIS S.R.O.
ŠPANIELOVA 1315/25
163 00 PRAHA 6 - ŘEPY
CZECH REPUBLIC

ORG. ID 64940799
VAT ID CZ64940799
C 42174 MĚSTSKÝ SOUD
V PRAZE

TEL +420 567 211 517
TECHNICAL@BROKIS.CZ
INFO@BROKIS.CZ
WWW.BROKIS.CZ



CLEANING THE GLASS

BROKIS upholds only the highest possible quality standards. Prior to shipping, the light undergoes several quality controls and stages of cleaning. Because transportation, storage, and the amount of time that passes between packing at our plant and subsequent unpacking by the client can affect the light in different ways, we strongly recommend cleaning it prior to assembly.


The glass must first be rinsed in warm water, and a dish detergent may be used to remove all foreign particles, dust, and grease. Repeat the process if necessary and then dry the glass thoroughly with a paper towel. Recommendation: Do not use mineral spirits, highly concentrated thinners, or other substances not intended for use on glass surfaces. Do not use any cleaning agents containing silicone, as they may leave a film and attract dust and smudges.

PRIOR TO SHIPPING, THE FUNCTIONALITY OF EACH LIGHT AND ITS COMPONENTS IS THOROUGHLY TESTED. THE MANUFACTURER ASSUMES NO LIABILITY FOR THE MISHANDLING OF PRODUCTS.




1. INSTALLING THE CEILING BRACKET

Using anchors of sufficient strength (not included), secure the bracket to the ceiling in three points. With regard to various types of ceilings, we recommend consulting installation with an expert. The manufacturer assumes no liability for incorrect installation, the use of improper anchors, or defects in the material to which the bracket is secured.




2. HANGING THE CEILING CANOPY

Use the three installation hooks to hang the ceiling canopy on the bracket.




3. INSTALLING THE STAINLESS-STEEL WIRE ROPES

First, pass the wire ropes through the holes in the fixture cover. Next, loosen the cylinders on wire rope stops in the ceiling canopy and pass the wire ropes through them to the required length (ensure the ends of the wire ropes are not frayed). Pass the wire ropes through the second part of the cylinders. Finally, pass the wire ropes through the locking tabs in the ceiling canopy and attach the brass balls to them using the 1.5 hex key. Adhering to these steps ensures safe anchoring of the wire ropes.




4. INSTALLING THE POWER CABLE

Pass the power cable with connector through the opening in the canopy, adjust its length, and then secure it with a plastic cable stop.




5. ELECTRICAL CONNECTION

Connect the light to the building wiring according to the connection diagram.




6. INSTALLING THE CEILING CANOPY

Remove the installation hooks. Using the three set screws (M5×16) and the size 2.5 hex key, attach the ceiling canopy to the bracket.




7. INSTALLING THE LIGHT SOURCE

Install the light source. Insert the fixture with light source into the glass shade and secure it with the four screws (M3×6) using hex key size 2.




8. INSTALLING THE LIGHT 1/3

Pass the power cable through the fixture cover. With an assistant holding the glass shade, lift the fixture cover and hook the brass balls on the end of the stainless-steel wire ropes into the N-shaped cutouts. The brass balls must be seated firmly at the round end of the cutout.




9. INSTALLING THE LIGHT 2/3

Loosen the M3 set screw with the size 1.5 hex key on the power cable connector. Insert the power cable connector into the connector on the light and secure the sleeve by retightening the set screw.




10. INSTALLING THE LIGHT 3/3

Connect the ground wire on the fixture cover using the connector.



11. LEVELLING THE LIGHT

Check the alignment of the light by placing the provided spirit level on the fixture cover. Make small adjustments to the length of the wire ropes by pressing the safety stops installed inside the canopy. Once the light is level, secure the safety stops by retightening them.



12. SWITCHING ON THE LIGHT

Restore power at the main circuit panel and verify that the light works properly.

